ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli
Street ID	**Street Name**	**Significant Landmark**
W0474, W0687, W0466	4th Crs, NA, 1st Main Rd	Balaji Layout Storm Water Drain
Segment No.	**Total Length (m)**	
8/C-W0474/S012400	225.73	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	64.46	77.578096	13.050042	77.578678	13.049924	3rd Cross	Main Road
2	81.01	77.577230	13.050206	77.577965	13.050076	3rd Cross	Main Road
3	80.26	77.577200	13.049940	77.577924	13.049791	2nd Cross	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and Main and Cross Roads of Kodigehalli and Surrounding areas in Ward No 08, Kodigehalli	6000000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender	1.Construction of RCC Drains.2.Providing and laying RCC Covering Slabs.3.Providing Kerb Stones.4.Construction of Culverts	008-20-000070
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/137/2020-21	19/11/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
15/02/2021	14/02/2024	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Byate Gowda S N		0.00
Phone No.	**E-Mail ID**	
7019666667		

Assistant Executive Engineer
Kodigehalli Sub Division
BBMP, Bangalore

Inspection Details

Number of Trees	Any Other Information	Name
0		Praveen A.R

Date of Inspection	Remarks
13/08/2021	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	S.P.Ranganath	23/08/2021	12/09/2021	As proposed
SE	Vijay Kumar Haridas	19/08/2021	12/09/2021	Forwarded
EE	Mohan Das H T	19/08/2021	12/09/2021	Forwarded
AEE	Srinivas Murthy	13/08/2021	12/09/2021	Verified

Zone: YELAHANKA Ward No: 8 Ward Name: Kodigehalli Street ID: W0474, W0687, W0466

Assistant Executive Engineer
Kodigehalli Sub Division
BBMP, Bangalore

	Praveen A R	13/08/2021	12/09/2021	Mobile verification Done
AE	Praveen A R	13/08/2021	12/09/2021	Forwarded

Assistant Executive Engineer
Kodigehalli Sub Division
BBMP, Bangalore

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0474, W0687, W0466